

R-400 Lamp Series Directions For Use

1. Unscrew the base of the lamp.
2. Unscrew wick holder and remove.
3. Fill reservoir with Kerosene based, refined, high quality lamp oil - $\frac{3}{4}$ full only.
4. Wick setting should be level with wick holder and no higher than 2mm.
5. Replace wick holder and light
6. Screw base back onto lamp.

To Extinguish

1. Blow through vent hole at back of lamp. (Care should be taken handling the top half of the lamp which will be hot after use.)

Caution

1. It is highly dangerous to burn any substance other than kerosene (also known as paraffin) in the lamp. Under NO circumstances should any other fuel be used.
2. This lamp is designed for use as a lighted ornament only. The lamp does not contain the filters and seals found in a genuine miner's lamp and therefore should NEVER be used in circumstances where a naked flame would be dangerous.

It is important to follow the above instruction to safely enjoy the benefits of your lamp. Use recommended metal polish to clean the lamp.